

THE RED THERMO SECURED "SP" LOGO IN THE LOWER CORNER OF THIS CHECK MUST FADE TEMPORARILY WHEN WARMED BY TOUCH OR FRICTION. SEE BACK FOR ADDITIONAL FEATURES.

BOWIE FIRE DISTRICT/WARRANT

P.O. BOX 241
BOWIE, AZ 85605

DATE Aug 21, 2023 **01401329**
66-156/531

PAY
TO THE
ORDER OF

Jarod's AUTO and Tire

\$ 5828.⁸⁷

Five Thousand Eight hundred Twenty Eight + ⁸⁷/₁₀₀ DOLLARS

Modest Powell

Barbara Easton

WELLS FARGO Wells Fargo Bank, N.A.
Chapel Hill, NC

MEMO Little rescue repairs
Repair order # J003920

Mobile Deposit Safe Deposit Box

⑈01401329⑈

SUPERIOR PRESS • 888-290-7698
CHRYSLER FINANCIAL GROUP

Bowie Fire District (BOW007)

Po Box 241
 118 W Kinchilla
 Bowie AZ 85605

Work: 520-847-2553
 bowiefiredistrict@proton.me

2007 Ford F-550 Super Duty Lariat
 6.0 DIESEL
 1FDAF57PX7EA84730
 5R110W

License Plate: G494FY AZ

Miles In: 63,663
 Miles Out: 63,663

WORK TO BE PERFORMED

Labor

Labor	Tech	Hrs	Price	Total
service call to look at fire truck has no start no oil pressure on dash or from high pressure pump .after testing found big air leak in oil system heui . under right side valve cover . was able to get started and drove back to shop for tear down of motor.		1.00	225.00	225.00
!st this is fire truck you cant do this job with out a lot of extra labor because you can not left the cab with out moving a lot of fire stuff and wiring so had to remove everything one piece at a time .remove both valve covers to gain access to oil rail on right side. remove top oil tube to gain access to seals that are blown out missing seal on lower stand pipe where loss of oil has been leaking most likely the no start right side lower stand pipe was stuck in the block removed upper oil tube to gain access to stand pipe .removed injectors for air leaking on seal resealed right side reinstalled injectors . removed turbo found small oil leak at base replaced the high pump . and ipr seal broken on back side . tore motor down two times had to test after fixing stand pipe seals .remove a/c evape core to be able to remove stand pipe and tubing housing side comes off for access to right head. remove wipe assembly housing from front windshield for more room .find and fix circuit ,		19.80	105.00	2,079.00
drive to Tucson AZ to find stand pipe replacement nonthin in stock found online power diesel .		3.00	85.00	255.00
evacuate and recharge a/c system after repair to stand pipe replacement and tube removal .		1.40	105.00	147.00
updated stand pipe assembly		1.00	299.99	299.99
injector seals upper and lower, after sealing oil pressure in motor check engine light still one found oil filter hose on wiring harness and the wires melted to icp sensor truck has running in limp mode for icp		1.00	231.45	231.45
remove and replace ipr valve old one was motorcraft		3.90	105.00	409.50

Parts	Part No	Qty	Price	Total
BRAKE CLEANER	AAAAAABRAKE	4.00	6.95	27.80
fuel preussure r gp ipr	AAA800-541	1.00	354.79	354.79
ipr socket	AAA001	1.00	39.99	39.99

SubTotal: Labor **\$4,069.52**

Parts

Parts	Part No	Qty	Price	Total
Diesel Injection Oil Pump	DRM502-560	1.00	1,359.35	1,359.35
CORE - Diesel Injection Oil Pump	DRM502-560	1.00	175.00	175.00
CORE CREDIT - Diesel Injection Oil Pump	DRM502-560	1.00	-175.00	-175.00

SubTotal: Parts **\$1,359.35**

Jarod's Auto and Tire

Tel: 520-766-1626

Bowie Fire District (BOW007) • 2007 Ford F-550 Super Duty Lariat

Repair Order J003920

Date: 08-04-2025 06:49 AM

Labor

Labor	Tech	Hrs	Price	Total
red/white flashing light bar installed on front bumper		1.00	225.00	225.00

SubTotal: Labor **\$225.00**

Labor	3,871.94
Parts	1,781.93
Hazmat*	25.00
Supplies*	150.00
Taxes	0.00

Repair Order Total **\$5,828.87**

* Shop Supply & Hazmat Fees: This charge represents costs and profits (where applicable) to this repair facility for miscellaneous shop supplies, and/or waste removal

AUTHORIZATION

Date/Time:	Authorizer	Method	Contact Details	Original Estimate Total
08-04-2025 06:49 AM	Bowie Fire District	In Person		1,195.00
<p>X _____ Customer Signature</p>				

Authorized
P&L
8/21
F 211

WF
CK# 01401389
Signed 8/29/25
(me)

Hand
Delivered
9-2-25
(me)